



Vehicle History Report™

US \$44.99

2013 LEXUS ES 350

VIN: JTHBK1GG3D2051755

SEDAN 4 DR

3.5L V6 F DOHC 24V

GASOLINE

FRONT WHEEL DRIVE



Accident reported: total loss vehicle



46 Service history records



3 Previous owners



Personal vehicle



Last owned in Wisconsin



220,314 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/14/25 at 5:03:27 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History

Not all accidents / issues are reported to CARFAX



Event 1

02/21/2014

Accident reported: severe damage

- Vehicle involved in a sideswipe collision with another motor vehicle
- Vehicle towed
- Airbag deployed

Damage Severity Scale




Event 2

01/24/2015

Accident reported



- Vehicle involved in a rear-end collision with another motor vehicle
- Airbags did not deploy



Event 3

12/15/2016

Damage reported: minor to moderate damage





Event 4

04/11/2018

Accident reported: minor to moderate damage with another motor vehicle


- Airbags did not deploy



Event 5

02/10/2021

Damage reported: minor damage





Event 6

09/25/2022

Accident reported: minor to moderate damage

- Involving front or side impact with another motor vehicle
- Disabling damage reported
- Vehicle towed
- Airbags did not deploy





Event 7

09/25/2022

TOTAL LOSS VEHICLE

- Vehicle declared a total loss by an insurance company
- Collision damage reported

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2	Owner 3
Total Loss Total Loss Reported: 09/25/2022.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	Total Loss Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment Airbag deployment reported: 02/21/2014.	<input checked="" type="checkbox"/> No Issues Reported	Airbag Deployment	No New Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Accidents reported: 02/21/2014, 01/24/2015, 04/11/2018, and 09/25/2022. Damage reported: 12/15/2016 and 02/10/2021.	<input checked="" type="checkbox"/> No Issues Reported	Severe Damage	Accident Reported
Manufacturer Recall No open recalls reported to CARFAX. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1	Owner 2	Owner 3
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2013	2013	2015
Type of owner	Personal	Personal	Personal
Estimated length of ownership	21 days	1 yr. 11 mo.	9 yrs. 6 mo.
Owned in the following states/provinces	Wisconsin	Wisconsin	Wisconsin
Estimated miles driven per year	---	21,631/yr	25,654/yr
Last reported odometer reading	97	44,309	220,314





Detailed History



Owner 1

Purchased: 2013

Personal Vehicle

Date	Mileage	Source	Comments
03/20/2013		NICB	Vehicle manufactured and shipped to Illinois
04/02/2013	12	Lexus of Arlington Arlington Heights, IL 847-991-0444 lexusofarlington.com ★ 4.8 / 5.0 450 Verified Reviews ♥ 38 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed
05/04/2013		Dealer Inventory	Vehicle offered for sale
05/13/2013		Lexus North Shore Infiniti North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews	Vehicle offered for sale
05/16/2013		Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews	Vehicle sold
05/16/2013		Wisconsin Motor Vehicle Dept. Mequon, WI	Titled or registered as personal vehicle
05/17/2013	95	Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews	 Vehicle serviced
06/01/2013	97	Wisconsin Motor Vehicle Dept. Mequon, WI Title #13152C5440182	Title issued or updated - Registration issued or renewed - First owner reported - Vehicle color noted as Black







Owner 2


Purchased: 2013

Personal Vehicle






21,631 mi/yr

Date	Mileage	Source	Comments
------	---------	--------	----------

06/06/2013	1,326	Wisconsin Motor Vehicle Dept. Mequon, WI		Odometer reading reported
06/11/2013		Wisconsin Motor Vehicle Dept. Mequon, WI Title #1316203720388		Title issued or updated <ul style="list-style-type: none">- Registration issued or renewed- New owner reported- Vehicle color noted as Black
08/06/2013	5,613	Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews		Vehicle serviced <ul style="list-style-type: none">- 5,000 mile service performed- Oil and filter changed- Tire condition and pressure checked- Tires rotated
11/05/2013	10,552	Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews		Vehicle serviced <ul style="list-style-type: none">- 10,000 mile service performed- Floor mat(s) checked- Fluids checked- Maintenance reminder reset- Oil and filter changed- Tire condition and pressure checked- Tires rotated
01/17/2014	15,456	Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews		Vehicle serviced <ul style="list-style-type: none">- Floor mat(s) checked- Tires rotated
02/21/2014		Damage Report		Accident reported: severe damage <ul style="list-style-type: none">- Vehicle involved in a sideswipe collision with another motor vehicle- Damage to left front- Damage to left side- Vehicle towed- Airbag deployed CARFAX Airbag Tips
<div><div><div>Damage Severity Scale</div><div><div></div><div></div><div></div></div><div>MINORMODERATESEVERE</div></div><div><div>Damage Location</div><div>FRONT</div><div>LEFTRIGHT</div></div></div>				



CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION

06/09/2014	20,785	Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews		Vehicle serviced - 20,000 mile service performed - Floor mat(s) checked
07/10/2014		Wisconsin Motor Vehicle Dept. Mequon, WI		Registration issued or renewed - Vehicle color noted as Black
08/26/2014	26,014	Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews		Vehicle serviced - Recommended maintenance performed - 25,000 mile service performed - Floor mat(s) checked
10/08/2014	28,747	Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews		Vehicle serviced - Engine/powertrain computer/module checked - Floor mat(s) checked
11/12/2014	31,282	Lexus North Shore Milwaukee, WI 414-228-9000 lexusnorthshore.com ★ 4.8 / 5.0 13 Verified Reviews		Vehicle serviced - Recommended maintenance performed - 30,000 mile service performed - 35,000 mile service performed - Floor mat(s) checked
01/22/2015	36,755	Lexus North Shore Milwaukee, WI		Vehicle serviced - Recommended maintenance performed

414-228-9000
lexusnorthshore.com
★ 4.8 / 5.0
13 Verified Reviews

- 35,000 mile service performed
- Body electrical system checked
- Floor mat(s) checked
- Wheels checked


01/24/2015

Damage Report



Accident reported

- Vehicle involved in a rear-end collision with another motor vehicle
- Damage to rear
- Airbags did not deploy



**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**

02/12/2015

37,966

Lexus North Shore
Milwaukee, WI
414-228-9000
lexusnorthshore.com
★ 4.8 / 5.0
13 Verified Reviews



Vehicle serviced

- Floor mat(s) checked

02/26/2015

39,286

Lexus North Shore
Milwaukee, WI
414-228-9000
lexusnorthshore.com
★ 4.8 / 5.0
13 Verified Reviews



Vehicle serviced

- Floor mat(s) checked

04/07/2015

41,509

Lexus North Shore
Milwaukee, WI
414-228-9000
lexusnorthshore.com
★ 4.8 / 5.0
13 Verified Reviews



Vehicle serviced

- Recommended maintenance performed
- 40,000 mile service performed
- 45,000 mile service performed
- Floor mat(s) checked

04/28/2015

42,836

Lexus North Shore
Milwaukee, WI
414-228-9000



Vehicle serviced

- Floor mat(s) checked


lexusnorthshore.com

★ 4.8 / 5.0

13 Verified Reviews




06/01/2015	44,293	Audi North Shore Milwaukee, WI 414-355-4400 audinorthshore.com ★ 4.6 / 5.0 315 Verified Reviews ❤️ 2,935 Customer Favorites	Vehicle offered for sale
------------	--------	---	--------------------------

06/02/2015		Dealer Inventory	Vehicle offered for sale
------------	--	------------------	--------------------------

07/13/2015	44,302	Brown Deer Sales Service Center Milwaukee, WI 414-357-6590 ★ 4.5 / 5.0 20 Verified Reviews ❤️ 31 Customer Favorites	 Vehicle serviced
------------	--------	---	--

07/27/2015	44,309	Auto Auction	Vehicle sold
------------	--------	--------------	--------------

 Owner 3 Purchased: 2015	Personal Vehicle 25,654 mi/yr
--	----------------------------------

Date	Mileage	Source	Comments
11/01/2015	44,319	Wisconsin Motor Vehicle Dept. Milwaukee, WI Title #15305D5670010	Title issued or updated - Registration issued or renewed - New owner reported - Loan or lien reported - Vehicle color noted as Black
12/22/2015	58,480	Lexus of Brookfield Brookfield, WI 262-797-2000 lexusofbrookfield.com/ ★ 4.6 / 5.0 706 Verified Reviews ❤️ 10,606 Customer Favorites	 Vehicle serviced - Drain plug gasket replaced - Oil and filter changed
04/22/2016	68,841	Lexus of Brookfield Brookfield, WI 262-797-2000 lexusofbrookfield.com/ ★ 4.6 / 5.0 706 Verified Reviews ❤️ 10,606 Customer Favorites	 Vehicle serviced - Air filter replaced - Floor mat(s) checked - Oil and filter changed
09/12/2016	79,224	Lexus of Brookfield Brookfield, WI 262-797-2000 lexusofbrookfield.com/	 Vehicle serviced - Drain plug gasket replaced - Oil and filter changed

★ 4.6 / 5.0
706 Verified Reviews
♥ 10,606 Customer Favorites

12/15/2016

Damage Report





Damage reported: minor to moderate damage

- Damage to front
- Damage to left front



**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**



01/27/2017 90,000 Wisconsin
Inspection Station

Passed emissions inspection

01/27/2017 Wisconsin
Motor Vehicle Dept.
Milwaukee, WI

Registration issued or renewed
- Vehicle color noted as Black

02/10/2017 91,077 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com/

★ 4.6 / 5.0
706 Verified Reviews
♥ 10,606 Customer Favorites



Vehicle serviced

- Air filter checked
- Brake pads replaced
- Brake rotor(s) resurfaced
- Brakes serviced
- Cabin air filter replaced/cleaned
- Drain plug gasket replaced
- Front wiper blades/refills replaced
- Oil and filter changed
- Rear brake pads replaced
- Tires rotated
- Wiper(s) replaced


03/06/2017 93,160 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com/




Vehicle serviced

★ 4.6 / 5.0
706 Verified Reviews
♥ 10,606 Customer Favorites

04/19/2017 96,972 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
★ 4.6 / 5.0
706 Verified Reviews
♥ 10,606 Customer Favorites

 **Vehicle serviced**
- Front brake rotor(s) replaced


06/15/2017 100,810 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
★ 4.6 / 5.0
706 Verified Reviews
♥ 10,606 Customer Favorites

 **Vehicle serviced**
- Recommended maintenance performed

08/28/2017 106,380 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
★ 4.6 / 5.0
706 Verified Reviews
♥ 10,606 Customer Favorites

 **Vehicle serviced**
- Alignment performed
- Oil and filter changed
- Tire(s) balanced
- Tire(s) mounted
- Two tires balanced
- Two tires mounted

11/06/2017 112,414 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
★ 4.6 / 5.0
706 Verified Reviews
♥ 10,606 Customer Favorites

 **Vehicle serviced**
- Oil and filter changed

12/20/2017 Wisconsin
Motor Vehicle Dept.
Milwaukee, WI

Registration issued or renewed
- Vehicle color noted as Black

02/05/2018 119,392 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
★ 4.6 / 5.0
706 Verified Reviews
♥ 10,606 Customer Favorites

 **Vehicle serviced**
- Oil and filter changed

02/23/2018 Wisconsin
Motor Vehicle Dept.
Milwaukee, WI

Registration issued or renewed
- Vehicle color noted as Black

04/11/2018 Damage Report

 **Accident reported: minor to moderate damage with another motor vehicle**
- Damage to front

- Damage to left front
- Damage to left side
- Airbags did not deploy




**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**

Damage Severity Scale



Damage Location



04/12/2018 126,478 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
★ 4.6 / 5.0
706 Verified Reviews
❤️ 10,606 Customer Favorites



Vehicle serviced
- Oil and filter changed

10/05/2018 136,503 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
★ 4.6 / 5.0
706 Verified Reviews
❤️ 10,606 Customer Favorites



Vehicle serviced
- Drive belt(s) replaced
- Oil and filter changed

01/29/2019 144,692 Service Facility
★ 4.5 / 5.0
33 Verified Reviews
❤️ 1 Customer Favorite



Vehicle serviced
- Tire(s) replaced

03/20/2019 147,891 Service Facility
★ 4.5 / 5.0
33 Verified Reviews
❤️ 1 Customer Favorite









Vehicle serviced
- Tire(s) replaced

06/24/2019 154,000 Wisconsin

Passed emissions inspection

Inspection Station

06/24/2019		Wisconsin Motor Vehicle Dept. Milwaukee, WI		Registration issued or renewed - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as Black
08/09/2019	157,159	Lexus of Brookfield Brookfield, WI 262-797-2000 lexusofbrookfield.com ★ 4.6 / 5.0 706 Verified Reviews ❤️ 10,606 Customer Favorites		Vehicle serviced - Oil and filter changed
01/08/2020	163,371	Lexus of Brookfield Brookfield, WI 262-797-2000 lexusofbrookfield.com ★ 4.6 / 5.0 706 Verified Reviews ❤️ 10,606 Customer Favorites		Vehicle serviced - Engine checked
01/31/2020		Wisconsin Motor Vehicle Dept. Milwaukee, WI		Registration issued or renewed - Vehicle color noted as Black
03/27/2020	166,388	Russ Darrow Chrysler Dodge Jeep of Milwaukee Milwaukee, WI 414-404-8277 russdarrowchrysler.net/ ★ 4.4 / 5.0 330 Verified Reviews ❤️ 2,242 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
07/01/2020	171,420	Lexus of Brookfield Brookfield, WI 262-797-2000 lexusofbrookfield.com ★ 4.6 / 5.0 706 Verified Reviews ❤️ 10,606 Customer Favorites		Vehicle serviced - Oil and filter changed
09/05/2020	175,224	Lexus of Milwaukee Milwaukee, WI 414-228-9000 https://lexusofmilwaukee.com ★ 4.6 / 5.0 529 Verified Reviews ❤️ 7,071 Customer Favorites		Vehicle serviced - Brakes checked - Tires rotated
10/01/2020	176,594	Lexus of Milwaukee Milwaukee, WI 414-228-9000		Vehicle serviced - Air filter replaced - Brake fluid flushed/changed

<https://lexusofmilwaukee.com>

★ 4.6 / 5.0

529 Verified Reviews

♥ 7,071 Customer Favorites

- Cabin air filter replaced/cleaned
- Sway bar bushing(s) replaced

11/19/2020

179,646

Lexus of Milwaukee
Milwaukee, WI
414-228-9000
<https://lexusofmilwaukee.com>

★ 4.6 / 5.0

529 Verified Reviews

♥ 7,071 Customer Favorites



Vehicle serviced

- Front brake pads replaced
- Front brake rotor(s) replaced
- Lug nut(s)/bolt(s) replaced
- Rear brakes serviced/adjusted
- Vehicle washed/detailed

12/07/2020

180,000

Wisconsin
Inspection Station

Passed emissions inspection

12/07/2020

Wisconsin
Motor Vehicle Dept.
Milwaukee, WI

Registration issued or renewed

- Registration updated when owner moved the vehicle to a new location
- Vehicle color noted as Black

12/22/2020

182,111

Sam's Club Tire & Battery
Center
Milwaukee, WI
414-365-3700
<https://www.samsclub.com>

★ 4.5 / 5.0

33 Verified Reviews

♥ 1 Customer Favorite



Vehicle serviced

- Tire(s) balanced
- Tires rotated

01/29/2021

184,013

Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com

★ 4.6 / 5.0

706 Verified Reviews

♥ 10,606 Customer Favorites



Vehicle serviced


- Oil and filter changed

02/10/2021

Damage Report



Damage reported: minor damage



04/26/2021

189,501

Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com


★ 4.6 / 5.0



706 Verified Reviews



Vehicle serviced



- Oil and filter changed

 **10,606** Customer Favorites

07/01/2021 194,674 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
 **4.6 / 5.0**
706 Verified Reviews
 **10,606** Customer Favorites





Vehicle serviced
- Oil and filter changed

10/11/2021 200,704 Russ Darrow Chrysler
Dodge Jeep of Milwaukee
Milwaukee, WI
414-404-8277
russdarrowchrysler.net/
 **4.4 / 5.0**
330 Verified Reviews
 **2,242** Customer Favorites




Vehicle serviced
- Inspection performed
- Alignment checked
- Tire checked
- Maintenance inspection completed
- Oil and filter changed

11/04/2021 202,301 Sam's Club Tire & Battery
Center
Milwaukee, WI
414-365-3700
https://www.samsclub.com
 **4.5 / 5.0**
33 Verified Reviews
 **1** Customer Favorite





Vehicle serviced
- Tire(s) replaced

12/08/2021 Wisconsin
Motor Vehicle Dept.
Milwaukee, WI
Registration issued or renewed
- Vehicle color noted as Black

12/20/2021 205,806 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
 **4.6 / 5.0**
706 Verified Reviews
 **10,606** Customer Favorites





Vehicle serviced
- Oil and filter changed

02/24/2022 210,625 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
 **4.6 / 5.0**
706 Verified Reviews
 **10,606** Customer Favorites



Vehicle serviced
- Air filter replaced
- Cabin air filter replaced/cleaned
- Drive belt(s) replaced
- Oil and filter changed

06/30/2022 216,036 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
 **4.6 / 5.0**
706 Verified Reviews
 **10,606** Customer Favorites



Vehicle serviced
- Oil and filter changed

09/09/2022 220,314 Lexus of Brookfield
Brookfield, WI
262-797-2000
lexusofbrookfield.com
★ 4.6 / 5.0
706 Verified Reviews
❤️ 10,606 Customer Favorites



Vehicle serviced

- Oil and filter changed
- Transmission fluid changed

09/25/2022

Damage Report



Accident reported: minor to moderate damage

- Involving front or side impact with another motor vehicle
- Damage to left front
- Damage to front
- Disabling damage reported
- Vehicle towed
- Airbags did not deploy




**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**

Damage Severity Scale



Damage Location



09/25/2022

Damage Report



TOTAL LOSS VEHICLE

- Vehicle declared a total loss by an insurance company
- Collision damage reported



There are many reasons an insurance company will declare a vehicle a total loss. Have this vehicle inspected by a qualified technician before you buy.
[Learn More](#)

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/14/25 at 5:03:27 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Airbag Deployment

Occurs when the driver, passenger or side airbag has been used or deployed during a crash or other incident. If an airbag has been deployed, it must be replaced by a qualified technician. Have this car inspected by a mechanic prior to purchase.

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/14/25 at 5:03:27 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Lexus Recall / Service Campaign

Portions of this report have been included under license from Toyota Motor North America, Inc. ("TOYOTA"), License Agreement TMS1013. This data applies only to vehicle marketed or originally sold in Mexico and the United States of America, including Guam, Saipan, American Samoa, Puerto Rico, the U.S. Virgin Islands and the other United States territories and protectorates with currently open safety or emissions recalls, or service campaigns. While TOYOTA provides data to Carfax Inc. on a regular basis, this report may not include very recent activity. For the manufacturer's most current information on recall/campaign activity for any Toyota, Lexus or Scion brand vehicle, you must go to <http://toyota.com/recall> or <http://lexus.com/recall>.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Total Loss Vehicle

An insurance or fleet company declares a vehicle a total loss when a claim exceeds approximately 75% of its pre-damage value or if the vehicle is stolen and not recovered. This damage threshold varies by company. These companies typically take possession and obtain the title. Not all total loss vehicles result in a DMV-reported branded title. This may occur when an insurance company's definition of a total loss is different than the state DMV's definition for a branded title or when the owner of the vehicle is a self-insured company, like a fleet or rental company.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved.
5/14/25 5:03:27 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2013 LEXUS ES 350 vehicle (VIN: JTHBK1GG3D2051755), which is based on information supplied to CARFAX and available as of 5/14/25 at 6:03 AM (EDT).

Customer Signature	Date	Dealer Signature	Date
--------------------	------	------------------	------