



# Vehicle History Report™

US \$44.99

## 1991 MERCEDES-BENZ 300-CLASS 300 E

VIN: WDBEA30D1MB363097  
SEDAN 4 DR  
3.0L I6 F  
GASOLINE  
REAR WHEEL DRIVE

### Accident reported: very minor damage



MINOR      MODERATE      SEVERE



23 Service history records



48 Detailed records available



281,228 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/6/25 at 1:17:20 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



## Accident / Damage History

Not all accidents / issues are reported to CARFAX

### Event 1

08/03/2006


### Accident reported: very minor damage

- Vehicle involved in crash
- Involving front or side impact
- Airbags did not deploy

#### Damage Severity Scale



MINOR      MODERATE      SEVERE



## Additional History

Not all accidents / issues are reported to CARFAX

### Summary

#### Total Loss

No total loss reported to CARFAX.



No Issues Reported

#### Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.



No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

#### Odometer Check

No indication of an odometer rollback.



No Issues Indicated

#### Accident / Damage

Accident reported: 08/03/2006.

Very Minor Damage

|                                                                       |                                                                                                         |
|-----------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|
| <b>Manufacturer Recall</b><br>No open recalls reported to CARFAX.     |  No Recalls Reported |
| <b>Basic Warranty</b><br>Original warranty estimated to have expired. | <b>Warranty Expired</b>                                                                                 |

|                                                                                                       |                |
|-------------------------------------------------------------------------------------------------------|----------------|
|  <b>Title History</b> | <b>Summary</b> |
| <b>Damage Brands</b><br>Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon                        | No Problem     |
| <b>Odometer Brands</b><br>Not Actual Mileage   Exceeds Mechanical Limits                              | No Problem     |

|  <b>Detailed History</b> |         |                                                  |                                                                                     |                                                                                   |
|----------------------------------------------------------------------------------------------------------|---------|--------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| Date                                                                                                     | Mileage | Source                                           |                                                                                     | Comments                                                                          |
| 04/20/1994                                                                                               | 52,649  | California Inspection Station Belmont, CA        |                                                                                     | <b>Passed emissions inspection</b>                                                |
| 05/15/1994                                                                                               | 53,542  | California Motor Vehicle Dept.                   |                                                                                     | <b>Title or registration issued</b><br>- Titled or registered as lease vehicle    |
| 12/07/1995                                                                                               | 70,639  | California Inspection Station Belmont, CA        |                                                                                     | <b>Passed emissions inspection</b>                                                |
| 04/07/1997                                                                                               | 82,190  | California Motor Vehicle Dept. San Francisco, CA |                                                                                     | <b>Odometer reading reported</b>                                                  |
| 04/10/1997                                                                                               | 82,191  | California Inspection Station Belmont, CA        |                                                                                     | <b>Passed emissions inspection</b>                                                |
| 04/24/1997                                                                                               |         | California Motor Vehicle Dept.                   |                                                                                     | <b>Title issued or updated</b><br>- New owner reported<br>- Loan or lien reported |
| 11/24/1998                                                                                               | 103,819 | Service Facility San Rafael, CA                  |  | <b>Vehicle serviced</b>                                                           |
| 11/24/1998                                                                                               |         | California Inspection Station San Rafael, CA     |                                                                                     | <b>Passed emissions inspection</b>                                                |
| 02/26/2000                                                                                               |         | California Motor Vehicle Dept. San Francisco, CA |                                                                                     | <b>Title issued or updated</b>                                                    |
| 12/26/2000                                                                                               | 117,140 | Service Facility San Francisco, CA               |  | <b>Vehicle serviced</b>                                                           |

|            |         |                                                                                                                         |   |                                                                                |
|------------|---------|-------------------------------------------------------------------------------------------------------------------------|---|--------------------------------------------------------------------------------|
| 12/26/2000 |         | California<br>Inspection Station<br>San Francisco, CA                                                                   |   | <b>Passed emissions inspection</b>                                             |
| 08/03/2001 | 119,968 | Mercedes-Benz of San Francisco<br>San Francisco, CA<br>415-673-2000<br>sfbenz.com<br>★ 4.3 / 5.0<br>22 Verified Reviews | 🔧 | <b>Vehicle serviced</b>                                                        |
| 10/23/2001 | 121,372 | Mercedes-Benz of San Francisco<br>San Francisco, CA<br>415-673-2000<br>sfbenz.com<br>★ 4.3 / 5.0<br>22 Verified Reviews | 🔧 | <b>Vehicle serviced</b><br>- Brakes checked<br>- Engine oil/fluid leak checked |
| 12/14/2002 | 132,391 | Service Facility<br>San Francisco, CA                                                                                   | 🔧 | <b>Vehicle serviced</b>                                                        |
| 01/01/2003 |         | California<br>Motor Vehicle Dept.<br>San Francisco, CA                                                                  |   | <b>Title issued or updated</b><br>- New owner reported                         |
| 12/02/2004 | 145,209 | California<br>Inspection Station                                                                                        |   | <b>Passed emissions inspection</b>                                             |

08/03/2006

Damage Report

🚗🔍

**Accident reported: very minor damage**

- Vehicle involved in crash
- Involving front or side impact
- Damage to right side
- Airbags did not deploy



Damage Severity Scale

MINOR

MODERATE

SEVERE


Damage Location

FRONT

LEFT

RIGHT

REAR



CARFAX HAS THE MOST  
ACCIDENT & DAMAGE

## INFORMATION



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

|            |         |                                                                                                                 |                                                                                                                                                                                                                                 |
|------------|---------|-----------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 11/28/2006 | 160,819 | California<br>Inspection Station                                                                                | <b>Passed emissions inspection</b>                                                                                                                                                                                              |
| 12/02/2008 | 177,304 | California<br>Inspection Station                                                                                | <b>Passed emissions inspection</b>                                                                                                                                                                                              |
| 10/01/2010 | 195,448 | California<br>Inspection Station<br>San Francisco, CA                                                           | <b>Passed emissions inspection</b>                                                                                                                                                                                              |
| 11/15/2012 | 213,408 | California<br>Inspection Station<br>Daly City, CA                                                               | <b>Passed emissions inspection</b>                                                                                                                                                                                              |
| 12/04/2014 | 223,540 | California<br>Inspection Station<br>Daly City, CA                                                               | <b>Passed emissions inspection</b>                                                                                                                                                                                              |
| 09/26/2016 | 235,559 | California<br>Inspection Station<br>Daly City, CA                                                               | <b>Passed emissions inspection</b>                                                                                                                                                                                              |
| 11/10/2016 | 236,892 | At The Shop<br>San Mateo, CA<br>650-574-1377<br>★ 4.9 / 5.0<br>51 Verified Reviews<br>❤️ 200 Customer Favorites | <br><b>Vehicle serviced</b><br>- Brake fluid flushed/changed<br>- Brakes serviced<br>- Front brake pads replaced<br>- Oil and filter changed |
| 03/18/2017 | 239,892 | At The Shop<br>San Mateo, CA<br>650-574-1377<br>★ 4.9 / 5.0<br>51 Verified Reviews<br>❤️ 200 Customer Favorites | <br><b>Vehicle serviced</b><br>- Coolant level sensor replaced<br>- Oil and filter changed                                                   |
| 07/26/2017 | 242,068 | At The Shop<br>San Mateo, CA<br>650-574-1377<br>★ 4.9 / 5.0<br>51 Verified Reviews<br>❤️ 200 Customer Favorites | <br><b>Vehicle serviced</b><br>- Oil and filter changed                                                                                      |
| 11/18/2017 | 244,093 | At The Shop<br>San Mateo, CA<br>650-574-1377<br>★ 4.9 / 5.0<br>51 Verified Reviews<br>❤️ 200 Customer Favorites | <br><b>Vehicle serviced</b><br>- Drive belt tensioner replaced                                                                               |

|            |         |                                                                                                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                                                                                      |
|------------|---------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 01/06/2018 | 245,105 | At The Shop<br>San Mateo, CA<br>650-574-1377<br> <b>4.9 / 5.0</b><br>51 Verified Reviews<br> <b>200</b> Customer Favorites     |  <b>Vehicle serviced</b><br>- Oil and filter changed                                                                                                                                                                                                                |
| 07/21/2018 | 249,452 | At The Shop<br>San Mateo, CA<br>650-574-1377<br> <b>4.9 / 5.0</b><br>51 Verified Reviews<br> <b>200</b> Customer Favorites     |  <b>Vehicle serviced</b><br>- Air filter replaced<br>- Oil and filter changed                                                                                                                                                                                       |
| 10/12/2018 | 251,871 | California<br>Inspection Station<br>Daly City, CA                                                                                                                                                                                                                                                | <b>Passed emissions inspection</b>                                                                                                                                                                                                                                                                                                                   |
| 12/01/2018 | 252,504 | At The Shop<br>San Mateo, CA<br>650-574-1377<br> <b>4.9 / 5.0</b><br>51 Verified Reviews<br> <b>200</b> Customer Favorites     |  <b>Vehicle serviced</b><br>- Oil and filter changed                                                                                                                                                                                                                |
| 04/10/2019 |         | At The Shop<br>San Mateo, CA<br>650-574-1377<br> <b>4.9 / 5.0</b><br>51 Verified Reviews<br> <b>200</b> Customer Favorites |  <b>Vehicle serviced</b><br>- Brakes checked<br>- Brake pads replaced<br>- Front brake pads replaced<br>- Left tie rod end replaced<br>- Stabilizer bar bushings replaced<br>- Steering/suspension checked<br>- Tie rod end(s) replaced                           |
| 04/20/2019 | 256,256 | At The Shop<br>San Mateo, CA<br>650-574-1377<br> <b>4.9 / 5.0</b><br>51 Verified Reviews<br> <b>200</b> Customer Favorites |  <b>Vehicle serviced</b><br>- Four tires balanced<br>- Four tires mounted<br>- Instrument cluster checked<br>- Instrument cluster replaced/repared<br>- One tire replaced<br>- Tire(s) replaced<br>- Washer fluid reservoir replaced<br>- Wipers/washers serviced |
| 07/15/2019 |         | Service Facility                                                                                                                                                                                                                                                                                 |  <b>Vehicle reconditioned</b>                                                                                                                                                                                                                                     |
| 08/16/2019 | 259,371 | At The Shop<br>San Mateo, CA<br>650-574-1377<br> <b>4.9 / 5.0</b><br>51 Verified Reviews<br> <b>200</b> Customer Favorites |  <b>Vehicle serviced</b><br>- Antifreeze/coolant checked<br>- Antifreeze/coolant flushed/changed<br>- Drivability/performance checked<br>- Thermostat replaced<br>- Water pump gasket replaced<br>- Water pump replaced                                           |
| 11/05/2019 | 261,052 | At The Shop<br>San Mateo, CA                                                                                                                                                                                                                                                                     |  <b>Vehicle serviced</b><br>- Brakes serviced                                                                                                                                                                                                                     |

650-574-1377

★ 4.9 / 5.0

51 Verified Reviews

♥ 200 Customer Favorites

- Oil and filter changed
- Rear brake pads replaced

02/17/2020

263,213

At The Shop  
San Mateo, CA  
650-574-1377

★ 4.9 / 5.0

51 Verified Reviews

♥ 200 Customer Favorites



#### Vehicle serviced

- Antifreeze/coolant flushed/changed
- Cooling system checked
- Cylinder head gasket(s) replaced
- Distributor cap replaced
- Distributor rotor replaced
- Engine checked
- Engine overhauled
- Oil and filter changed
- Piston rings replaced
- Radio/sound system checked
- Spark plug wires replaced
- Spark plug(s) replaced
- Thermostat replaced
- Timing chain replaced
- Timing chain tensioner/guide replaced
- Valve cover gasket(s) replaced
- Water pump gasket replaced
- Water pump replaced

09/29/2020

266,118

California  
Inspection Station  
Daly City, CA

#### Passed emissions inspection

07/13/2021

270,465

At The Shop  
San Mateo, CA  
650-574-1377

★ 4.9 / 5.0

51 Verified Reviews

♥ 200 Customer Favorites



#### Vehicle serviced

- Fluids checked
- Transmission fluid changed
- Transmission rebuilt

12/03/2021

272,634

At The Shop  
San Mateo, CA  
650-574-1377

★ 4.9 / 5.0

51 Verified Reviews

♥ 200 Customer Favorites



#### Vehicle serviced

- Oil and filter changed

11/08/2022

276,390

AUTOHAUS SCHMID  
Burlingame, CA  
650-342-2248  
autohausschmid.com/

★ 5.0 / 5.0

41 Verified Reviews

♥ 96 Customer Favorites



#### Vehicle serviced

- Emission system checked
- Idle control valve/motor replaced
- Relay replaced
- Throttle position sensor replaced

11/17/2022

276,620

California  
Inspection Station  
San Francisco, CA

#### Failed emissions inspection

11/18/2022

AUTOHAUS SCHMID  
Burlingame, CA



#### Vehicle serviced

- Fuel filler cap replaced

650-342-2248  
autohausschmid.com/  
★ 5.0 / 5.0  
41 Verified Reviews  
❤️ 96 Customer Favorites

|            |         |                                                                                                                          |                                                                                                                                                                           |
|------------|---------|--------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 11/21/2022 | 276,696 | California<br>Inspection Station<br>San Francisco, CA                                                                    | <b>Failed emissions inspection</b>                                                                                                                                        |
| 11/29/2022 | 276,787 | California<br>Inspection Station<br>San Francisco, CA                                                                    | <b>Passed emissions inspection</b>                                                                                                                                        |
| 05/03/2023 | 277,338 | Larkin Brothers<br>San Francisco, CA<br>415-863-5730<br>★ 4.9 / 5.0<br>262 Verified Reviews<br>❤️ 215 Customer Favorites |  <b>Vehicle serviced</b><br>- Alignment checked<br>- Tire condition and pressure checked |
| 10/11/2024 | 281,228 | California<br>Inspection Station<br>Burlingame, CA                                                                       | <b>Passed emissions inspection</b>                                                                                                                                        |
| 09/16/2025 |         | Auto Auction                                                                                                             | <b>Vehicle offered for sale</b>                                                                                                                                           |

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/6/25 at 1:17:20 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

### Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

**Lease**

When someone leases a car from a dealer, the dealer actually sells the vehicle to a leasing company. The leasing company then collects payments for the vehicle from the new owner for 24, 36, 48 or more months. A leasing company can be an independent car dealer or a car manufacturer.

**New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

**Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved.  
10/6/25 1:17:20 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 1991 MERCEDES-BENZ 300-CLASS vehicle (VIN: WDBEA30D1MB363097), which is based on information supplied to CARFAX and available as of 10/6/25 at 2:17 PM (EDT).

|                    |      |                  |      |
|--------------------|------|------------------|------|
| Customer Signature | Date | Dealer Signature | Date |
|--------------------|------|------------------|------|